Tesla, Inc.
5081 N Oracle Rd
Tucson,AZ,US 85704
Ph.: (520) 416: 7974

Invoice

SERVICE DEPARTMENT HOURS
Mon-Fri 0800 - 1900
Saturday-Sunday Sat 0800-1700, Sun Closed

Invoice date	Invoice number
24-Mar-2025	3000S0012670948
Due Date	
24-Mar-2025	
Date/Time Received	**Date/Time Promised**
17-Mar-2025 05:35:25	20-Mar-2025 17:00:40
Odometer In	**Odometer Out**
4300 Miles	4379 Miles
Ready Date	
20-Mar-2025 13:28:19	
Service Advisor	
Michael Hill	

Paid

Bill To
[redacted]

Mobile Phone	Additional Phone	Vehicle Identification Number
		[redacted]

Year	Model	License Plate Number	Colour
2024	CYBERTRUCK		

Job Number	Description Of Work	Amount (USD)
1	**Concern:** Customer states: Rattle or Squeak - Sorry , a pillar squeak isnt fixed **Repair Notes:** Performed validation test drive with customer to inspect noise concern, Customer identified rattle after vibrations on rough road conditions coming from front air ventilations under dash pad. Inspected air vent does have a rattle noise compared to a similar vehicle build. Removed and replaced air vent. Performed validation test drive on same roads and speed conditions as customer. Verified noise in concerned area is no longer present at this time. Some vibrations noises are acceptable as suspension and road conditions may very. **Correction: Adjustment: Interior Trim** **Correction: General Diagnosis** **Correction: Interior Ducting and Vents - IP Airwave Module - Remove and Replace** **Parts Replaced or Added** **Part** — **Quantity** IP AIRWAVE MODULE(1817432-00-I) — 1.00 **Correction: Perform Post-Repair Validation Test Drive** Pay Type: Basic Vehicle Limited Warranty	**0.00**
2	**Concern:** Check tire pressure and condition **Repair Notes:** A courtesy service was provided to check your tire pressure and condition, confirming all tires are correctly inflated and do not require rotation at this time.	**0.00**